

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/04/2023

Submitted Date:

01/06/2023

Document Number:

705000123

**FIELD INSPECTION FORM**

Loc ID 319747 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS INC  
Address: 370 17TH STREET SUITE 5200  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201247	WELL	SI	08/01/2020	GW	001-06650	COLLINS 14-20	PA
476909	OFF-LOCATION FLOWLINE	AC	11/14/2022		-	COLLINS-61S65W 20SWSW	EG

**General Comment:**

[COGCC Engineering Integrity Inspection; Flowline Inspection](#)  
[Photos uploaded](#)

**Inspected Facilities**

Facility ID: 201247 Type: WELL API Number: 001-06650 Status: SI Insp. Status: PA

Facility ID: 476909 Type: OFF- API Number: - Status: AC Insp. Status: EG

**Flowline**

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules (check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Well (Collins 14-20) has been plugged and abandoned; cut and cap operations are completed. COGCC form 42 notice of start of plugging operations doc #403224782 received 11/09/2022. COGCC form 42 flowline pre-abandonment notice doc #403209504 received 10/27/2022. No flowline risers observed at the (PA) wellhead or facility/ battery areas. The facility/ tank battery has been decommissioned; tanks and equipment removed. An OOS GMR is located on the east side of location. No Civitas personnel were on location at the time of inspection.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403275821 received on 12/30/2022: Historical impacts were discovered during decommissioning of the Collins 14-20 flowline and Collins HH-61S65W 20NENW tank battery. Soil samples exceeded COGCC standards at both locations. Historical impacts were discovered during decommission activities. AVO inspections occur routinely at all oil and gas facilities.	maclarej	01/06/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000125	Signage at location; OOS GMR	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5972922">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5972922</a>
705000126	Excavation at PA well; No FL risers	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5972923">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5972923</a>