



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	hog fence		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

**Equipment:**

Type	Equipment	Count	Comment	Corrective Action	Date	corrective date
Type: Pump Jack		# 1				
Comment:						
Corrective Action:					Date:	
Type: Ancillary equipment		# 1				
Comment:	electric panel					
Corrective Action:					Date:	
Type: Bradenhead		# 1				
Comment:	appears plumbed to surface					
Corrective Action:					Date:	
Type: Prime Mover		# 1				
Comment:	electric motor					
Corrective Action:					Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 240742 Type: WELL API Number: 123-08530 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 02/17/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Monday 1-9-2023 at approximately 1430 hrs. I, Inspector Robbie Revas,                      Conducted an on-site inspection:                      Operator: KP Kauffman                      Location name: Alex Dones unit 1                      API #05-123-08530                      County: Weld                      Weather: Cloudy/overcast.                      Location: snow covered.                      While there, I observed a wellsite, SI at the time of inspection.                      During this inspection, I observed no compliance issues:                      See attached photos.                      No follow up site inspection is needed to ensure that the addressed                      Compliance issues comply with COGCC rules.</p>	revasr	01/09/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702401373	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5975707">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5975707</a>