

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2023

Submitted Date:

01/03/2023

Document Number:

695107142

**FIELD INSPECTION FORM**Loc ID 333949 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261530	WELL	PR	09/01/2017	GW	071-07512	HEARTBEAT 44-30	PR
266002	WELL	PR	09/20/2021	CBM	071-07807	HEARTBEAT 44-30 TR	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment:

PHOTO 5: PACKING IS LEAKING ON TR WELLHEAD.

Corrective Action:

Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 01/04/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Deadman # &amp; Marked

# 6

Comment:

Corrective Action:

Date:

Type: Vertical Separator

# 2

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 2

Comment:

Corrective Action:

Date:

Type: Bradenhead

# 2

Comment:

BOTH ARE ACCESSABLE

Corrective Action:

Date:

Type: Gas Meter Run

# 2

Comment:

BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Ancillary equipment

# 2

Comment:

Corrective Action:

Date:

Type: Progressive Cavity

# 2

Comment:

Corrective Action:

Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**Facility ID: 261530 Type: WELL API Number: 071-07512 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 10/15/2015Annual Brhd Completed? Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 266002 Type: WELL API Number: 071-07807 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 10/15/2015Annual Brhd Completed? Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 270528Lat: 37.135909Long: -104.814440Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action: Date: Type: Produced WaterLined: NOPit ID: 264458Lat: 37.136204Long: -104.814925Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition:

Inspector Name: Beardslee, Tom

Comment:		Date:
Corrective Action		
Anchor Trench Present: <u>NO</u> Oil Accumulation: <u>NO</u> 2+ feet Freeboard: <u>YES</u>		
Comment:		Date:
Corrective Action		

### **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403278519	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5968657">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5968657</a>
695107143	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5968650">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5968650</a>