

Inspection Photos

API: 009-06504

Operator: MURFIN DRILLING COMPANY INC

Inspection Date: 1/10/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06504 | Date: 1/10/2023

Inspection Photos



Photo 1. Facing south toward the location. Perennial vegetation has established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06504 | Date: 1/10/2023

Inspection Photos



Photo 2. Facing north toward the location. Perennial vegetation has established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06504 | Date: 1/10/2023

Inspection Photos



Photo 3. There are pieces of pipe that remain at south side of the location that need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06504 | Date: 1/10/2023