

Inspection Photos

Loc ID: 321098

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 1/10/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 321098 | Date: 1/10/2023

Inspection Photos



Photo 1. Facing southwest toward the abandoned facility and well site which is approximately 3 acres in size.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 321098 | Date: 1/10/2023

Inspection Photos



Photo 2. There is a soil material pile that remains at the north side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 321098 | Date: 1/10/2023

Inspection Photos



Photo 3. The electric powerline utilities have not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 321098 | Date: 1/10/2023

Inspection Photos



Photo 4. There is a metal shed that remains at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 321098 | Date: 1/10/2023

Inspection Photos



Photo 5. Another soil material pile that remains at the south side of the location. There is a steel tank that remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 321098 | Date: 1/10/2023

Inspection Photos



Photo 6. East side of the location facing southwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 321098 | Date: 1/10/2023

Inspection Photos



Photo 7. Drone aerial photo facing west toward the [TANNER SEC REC UNIT #501](#) well site and production facility. The abandoned facility and well site has not been reclaimed and equipment remains. This image was taken during previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 321098 | Date: 1/10/2023