

Inspection Photos

API: 009-06439

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 1/10/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 1/10/2023

Inspection Photos



Photo 1. Facing southeast toward the location. There is a white pvc pipe extending out of the ground at the north side of the location..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 1/10/2023

Inspection Photos



Photo 2. Facing northeast near the location. There is cellar with pipeline valves northeast of the location that may have been associated with the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 1/10/2023

Inspection Photos



Photo 3. Facing south at the location. The location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 1/10/2023

Inspection Photos



Photo 4. Facing west at the south side of the location. This area consists mostly of undesirable weeds (Russian thistle, Kochia).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 1/10/2023

Inspection Photos



Photo 5. There is a plastic pipe sticking out of the ground approx. 200' southeast of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 1/10/2023

Inspection Photos



Photo 6. Facing toward the surrounding undisturbed reference area which consists of Blue grama, Sand dropseed, Prairie threeawn, among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06439 | Date: 1/10/2023