

Inspection Photos

API: 009-06498

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 1/10/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06498 | Date: 1/10/2023

Inspection Photos



Photo 1. Facing west toward the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06498 | Date: 1/10/2023

Inspection Photos



Photo 2. Facing west further along the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06498 | Date: 1/10/2023

Inspection Photos



Photo 3. The electric pole servicing the former will needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06498 | Date: 1/10/2023

Inspection Photos



Photo 4. Facing northwest at the location. This area approx. 15x15ft. Where the well was located has not re-established vegetation. Other areas of the location have established a uniform vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06498 | Date: 1/10/2023

Inspection Photos



Photo 5. Facing northwest toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06498 | Date: 1/10/2023