

Inspection Photos

API: 009-06464

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 1/10/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-064644 | Date: 1/10/2023

Inspection Photos



Photo 1. Facing north at the beginning of the access road which has not been reclaimed and the cattle guard remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-064644 | Date: 1/10/2023

Inspection Photos



Photo 2. The cattleguard needs to be removed and fence put back to original position.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-064644 | Date: 1/10/2023

Inspection Photos



Photo 3. Facing north along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-064644 | Date: 1/10/2023

Inspection Photos



Photo 4. Facing north at the location. There are areas of sparse vegetation and soils seem to be compacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-064644 | Date: 1/10/2023

Inspection Photos



Photo 5. Facing south at the location. There are areas of sparse vegetation and soils seem to be compacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-064644 | Date: 1/10/2023

Inspection Photos



Photo 6. Facing east toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-064644 | Date: 1/10/2023