

# Inspection Photos

API: 009-06454

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 1/10/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06454 | Date: 1/10/2023

## Inspection Photos



**Photo 1.** Facing southwest at the location. There are areas of sparse vegetation and soils are compacted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06454 | Date: 1/10/2023

## Inspection Photos



**Photo 2.** Facing southeast at the location. There are areas of sparse vegetation and soils are compacted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06454 | Date: 1/10/2023

## Inspection Photos



**Photo 3.** Facing back to the northwest at the location. There are areas of sparse vegetation and soils are compacted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06454 | Date: 1/10/2023

## Inspection Photos



**Photo 4.** The soils were not decompacted. The shovel shown in the photo could not penetrate the soil surface.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06454 | Date: 1/10/2023

## Inspection Photos



**Photo 5.** Facing northwest toward the surrounding undisturbed reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06454 | Date: 1/10/2023