

Inspection Photos

API: 009-06458

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 1/10/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06458 | Date: 1/10/2023

Inspection Photos



Photo 1. Facing south at the beginning of the access road. The cattle guard has not been removed and the road is not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06458 | Date: 1/10/2023

Inspection Photos



Photo 2. Facing south further along the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06458 | Date: 1/10/2023

Inspection Photos



Photo 3. Facing southwest toward the location. There is compacted soil where the two track road remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06458 | Date: 1/10/2023

Inspection Photos



Photo 4. Facing north at the location. This area approx. 15x15ft. Where the well was located has not re-established vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06458 | Date: 1/10/2023

Inspection Photos



Photo 5. Facing northwest toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06458 | Date: 1/10/2023