

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/13/2023

Submitted Date:

01/17/2023

Document Number:

701103675

FIELD INSPECTION FORM

Loc ID 427218 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10515
Name of Operator: GUNNISON ENERGY LLC
Address: 1801 BROADWAY #1150
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Johnston, Tyson		Tyson.Johnston@oxbow.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Kosola, Jason		jason.kosola@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483533	SPILL OR RELEASE	AC	12/26/2022		-	DGU 18H	EG

General Comment:

[Flowline Integrity Inspection.](#)

Inspected Facilities

Facility ID: 483533 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

Flowline

#1	Type:	1 of Lines
----	-------	------------

Flowline Description

Flowline Type: _____ Size: 4" Material: Carbon Steel
 Variance: _____ Age: _____ Contents: Produced Water

Integrity Summary

Failures: Other Spills: Yes Repairs Made: Yes
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Inspection in response to Form 19 Spill/release Report doc# 403271200
Cracked 4" suction line has been replaced.

Corrective Action: Document information outlined below on the CA section of COGCC supplemental form 19 spill report to include the following (compliance of COGCC series 1100 flowline rules):
1) Outline root cause of failure resulting in spill (1104.k. Integrity Failure Investigation/Operator Determination)
2) Measures taken to prevent a recurrence of failure (1102.I Corrosion Control/ 1104.Integrity Management)
3) Description of flowline repair work completed (1102.j. Repair)
4) Confirm integrity of flowline repairs/ reconnections (via pressure testing) prior to returning flowline to service (1102.j.4 and 1102.O)

Date: 02/10/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103676	Flowline integrity inspection 701103675 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5986528