

FORM  
INSPRev  
X/20

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/18/2023

Submitted Date:

01/18/2023

Document Number:

707900669

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
309551 \_\_\_\_\_ Silver, Randy \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10758  
Name of Operator: OGRIS OPERATING LLC  
Address: PO BOX 53467  
City: MIDLAND State: TX Zip: 79710

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email             | Comment |
|--------------|-------|-------------------|---------|
| ,            |       | gward@ogrisop.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 299643      | WELL | PR     | 08/01/2021  | CBM        | 071-09683 | APACHE CANYON 09-04 | PR          |

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
|                    |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           | ADequate |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

Comment:   
 Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                     | #              |  |  |       | corrective date |
|--------------------------|----------------|--|--|-------|-----------------|
| Type: Prime Mover        | # 1            |  |  |       |                 |
| Comment:                 | HYD motor skid |  |  |       |                 |
| Corrective Action:       |                |  |  | Date: |                 |
| Type: Gas Meter Run      | # 1            |  |  |       |                 |
| Comment:                 |                |  |  |       |                 |
| Corrective Action:       |                |  |  | Date: |                 |
| Type: Progressive Cavity | # 1            |  |  |       |                 |
| Comment:                 |                |  |  |       |                 |
| Corrective Action:       |                |  |  | Date: |                 |
| Type: Vertical Separator | # 1            |  |  |       |                 |
| Comment:                 |                |  |  |       |                 |
| Corrective Action:       |                |  |  | Date: |                 |
| Type: Bradenhead         | # 1            |  |  |       |                 |
| Comment:                 |                |  |  |       |                 |
| Corrective Action:       |                |  |  | Date: |                 |
| Type: Compressor         | # 1            |  |  |       |                 |
| Comment:                 |                |  |  |       |                 |
| Corrective Action:       |                |  |  | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 1 | OTHER    | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| <b>Paint</b>       |          |                     |                     |             |
| Condition          |          |                     |                     |             |
| Other (Content)    |          |                     |                     |             |
| Other (Capacity)   | 30bbl    |                     |                     |             |
| Other (Type)       |          |                     |                     |             |
| <b>Berms</b>       |          |                     |                     |             |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |
| <b>Venting:</b>    |          |                     |                     |             |
| Yes/No             | NO       |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |
| <b>Flaring:</b>    |          |                     |                     |             |
| Type               |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Inspected Facilities**

Facility ID: 299643 Type: WELL API Number: 071-09683 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/26/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment                            | User    | Date       |
|------------------------------------|---------|------------|
| <a href="#">Routine inspection</a> | silverr | 01/18/2023 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 707900670    | loc pic     | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5988418">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5988418</a> |