

# Interim Reclamation and Stormwater Inspection

Date: 01/13/2023

Operator: IMPERTO RESOURCES LLC - 10690

Location ID: 317038

Inspection Document #: 696105683

Washington County, CO

SENW Section 21 T2N R49W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Ray Walters  
Location ID: 317038



**Photo 1.** Facing south at tank battery. Tank NFPA placards are faded, cracking, and not legible.

Inspection Photos  
Location Name: Ray Walters  
Location ID: 317038



**Photo 2.** Facing northeast at tank battery. Tank NFPA placards are faded, cracking, and not legible.



**Photo 3.** Facing southeast at produced water tank. Tank NFPA placards are faded, cracking, and not legible.

Inspection Photos  
Location Name: Ray Walters  
Location ID: 317038



**Photos 4 & 5.** Facing north and east from the produced water tank. Evidence of rill erosion and animal burrows observed on the earthen berms.

Inspection Photos  
Location Name: Ray Walters  
Location ID: 317038



**Photos 6 & 7.** Facing northeast and north from produced water pits. Undesirable weedy vegetation observed throughout the location; weeds are now considered debris and need to be removed/managed.

Inspection Photos  
Location Name: Ray Walters  
Location ID: 317038



**Photo 8.** Facing south from the eastern portion of the pit walls. Photo illustrates that the pit walls have evidence of rill erosion. Due to snow cover, it is uncertain whether or not sediment laden stormwater has exited off location. This location will be inspected at a future date to reassess conditions.

Inspection Photos  
Location Name: Ray Walters  
Location ID: 317038




**Photo 9.** Facing northeast near the northeast corner of the pit. See comments in Photo 8.

Inspection Photos  
Location Name: Ray Walters  
Location ID: 317038



**Photo 10.** Facing west at the wellhead. Photo illustrates oily stained soil that will need to properly cleaned up.

Inspection Photos  
Location Name: Ray Walters  
Location ID: 317038



**Photo 11.** Facing south near the wellhead. Photo illustrates unused equipment being stored on location. This equipment will need to be removed.