

Interim Reclamation and Stormwater Inspection

Date: 01/13/2023

Operator: IMPETRO RESOURCES LLC - 10690

Location ID: 312277

Inspection Document #: 696105684

Washington County, CO

SWNW Section 21 T2N R49W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Photo 1. Facing northeast near the produced water tank. Photo illustrates the the western earthen berm has been breached with evidence of rill and gully erosion.

Inspection Photos
Location Name: Walters
Location ID: 317277



Photo 2. Facing south on the southern pit wall. Photo illustrates gully erosion (approx. 3' wide) on the exterior pit wall. A future inspection will be conducted to evaluate the off-location conditions as snow cover blocked view during this inspection.

Inspection Photos
Location Name: Walters
Location ID: 317277



Photo 3. Facing northeast at the southwest corner of the produced water pit. See comments in Photo 2.

Inspection Photos
Location Name: Walters
Location ID: 317277



Photo 4. Facing west from the western portion of the pit. Undesirable weedy vegetation was observed throughout the location and needs to be managed as it is now considered debris.



Photo 5. Facing southwest at the produced water tank. NFPA placards are inadequate and need to be replaced/installed.

Inspection Photos
Location Name: Walters
Location ID: 317277



Photo 6. Facing northwest at the wellhead. Unused equipment is being stored on site and needs to be removed.

Inspection Photos
Location Name: Walters
Location ID: 317277




Photo 7. Facing west near the wellhead. Photo illustrates oily stained soil that needs to be properly removed.

Inspection Photos
Location Name: Walters
Location ID: 317277



Photo 8. Facing north at wellhead. See comments in Photo 7.