

Interim Reclamation and Stormwater Inspection

Date: 01/13/2023

Operator: IMPETRO RESOURCES LLC - 10690

Location ID: 317278

Inspection Document #: 696105686

Washington County, CO

NWNE Section 15 T2N R49W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Chandler
Location ID: 317278



Photos 1 & 2. Facing southwest towards tanks. NFPA placards are either missing or not legible and need to be repaired/installed.

Inspection Photos
Location Name: Chandler
Location ID: 317278



Photos 3 & 4. Facing southwest at produced water tanks. NFPA placards are either missing or not legible (e.g. cracked, peeling, faded) and need to be replaced.



Photo 5. Facing south from the eastern pit wall. Photo illustrates rill erosion and unconsolidated material comprising the interior walls; e.g. not stabilized. Also pictured, undesirable weedy vegetation (e.g. kochia and russian thistle) that is considered debris and needs to be removed and managed for in the future.



Photo 6. Facing southwest from southeast corner of pit. See comments in Photo 5.



Photo 7. Facing east from southern pit wall. Photo illustrates the pit wall is unstabilized with evidence of rill erosion and unconsolidated material. These walls need to be repaired/stabilized to prevent further erosion from migrating off location.



Photo 8. Facing northeast from wellhead. Photo illustrates oil stained soil around wellhead that needs to be properly cleaned and disposed of.