

Interim Reclamation and Stormwater Inspection

Date: 01/09/2023

Operator: IMPETRO RESOURCES LLC - 10690

Location ID: 317256

Inspection Document #: 696105687

Washington County, CO

SENW Section 15 T2N R49W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Stennett
Location ID: 317256



Photos 1 & 2. Facing east at the tank battery location. NFPA placards are either missing or not legible and need to be installed on all tanks.

Inspection Photos
Location Name: Stennett
Location ID: 317256



Photos 3 & 4. Facing east at tank battery. Photos illustrates crude oil spill appearing to come from the top of the tank near the thief hatch. Also pictured, oil stained soil around the bottom of the tank.

Inspection Photos
Location Name: Stennett
Location ID: 317256



Photos 5 & 6. Facing northwest and east from the eastern side of the tank batteries. Photo illustrates oil stained soils that need to be properly removed and disposed of.



Photo 7. Facing north from inside of shed, north of skim pit. Photo illustrates oil stained soils coming from a leaky fitting.



Photo 8. Facing east from skim pit. Photo illustrates rill erosion occurring on the interior pit wall; these walls are not stabilized as the material is unconsolidated.

Inspection Photos
Location Name: Stennett
Location ID: 317256



Photos 9 & 10. Facing south and southwest from northern portion of the pit facilities. See comments in Photo 8.



Photo 11. Facing east from the northeastern corner of pit. Photo illustrates undesirable weedy vegetation (e.g. russian thistle and kochia); this is now considered debris and needs to be removed.