

# Inspection Photos

January 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 311608

Location Name: SHAEFFER-67S93W/12SENW

Inspection Document #: 702801159

Garfield County, CO

SENW Section 12 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: SHAEFFER-67S93W/12SENW  
Location ID: 311608



1/13/23  
+39.462566,-107.726917  
77° E



Photo 1. Photos show production areas.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801159



Inspection Photos  
Location Name: SHAEFFER-67S93W/12SENW  
Location ID: 311608



**Photo 2.** Photos show open ended piping at separators (left), an unused chemical tank (right).

## Inspection Photos

Location Name: SHAEFFER-67S93W/12SEW

Location ID: 311608



**Photo 3.** Photo shows two (2) risers which appear to be associated with plugged and abandoned well API #045-10452. Unused equipment must be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801159



## Inspection Photos

Location Name: SHAEFFER-67S93W/12SE NW

Location ID: 311608



**Photo 4.** Photos show stockpiled soil associated with plugged and abandoned well API #045-09128 (left) and the associated separator and flowline (right) excavations. Perimeter control berm does not appear properly compacted. Soils are loose, and susceptible to wind and water erosion and may act as a sediment source.

Inspection Photos  
Location Name: SHAEFFER-67S93W/12SEW  
Location ID: 311608



**Photo 5.** Photo shows an example of location interim areas. Introduced perennial grasses appear established.

