

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/17/2023

Submitted Date:

01/19/2023

Document Number:

707800110

FIELD INSPECTION FORM

 Loc ID 464958 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635
Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
465341	OFF-LOCATION FLOWLINE	AC	07/27/2021		-	Wellhead Line	AC
465342	OFF-LOCATION FLOWLINE	AC	07/27/2021		-	Wellhead Line	AC
465343	OFF-LOCATION FLOWLINE	AC	07/27/2021		-	Wellhead Line	AC
465344	OFF-LOCATION FLOWLINE	AC	07/27/2021		-	Wellhead Line	AC
465345	OFF-LOCATION FLOWLINE	AC	07/27/2021		-	Wellhead Line	AC

General Comment:[COGCC Inspection Report Summary](#)

On Tuesday 1/17/2022, I, Inspector Scott Ramsey, conducted a routine inspection at TEP PF 11-28, at Location # 464958 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

During this inspection the following compliance issues were observed:

1. Unused/stored equipment (ECD is disconnected)

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of fluid. Labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text" value="911"/>		Date: _____
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Unused/stored equipment (ECD is disconnected)		
Corrective Action:	Remove stored equipment		Date: <u>03/02/2023</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
			corrective date
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric heat trace pump mounted to the side of separator. Unknown if it is intrinsically safe.		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	See stored equipment for C/A		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 5	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	200 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 465341 Type: OFF- API Number: - Status: AC Insp. Status: AC

Facility ID: 465342 Type: OFF- API Number: - Status: AC Insp. Status: AC

Facility ID: 465343 Type: OFF- API Number: - Status: AC Insp. Status: AC

Facility ID: 465344 Type: OFF- API Number: - Status: AC Insp. Status: AC

Facility ID: 465345 Type: OFF- API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Ditches				
		Berms				
Berms						

Comment: [Limited storm water inspection due to snow cover](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800118	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5991476