

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2023

Submitted Date:

01/20/2023

Document Number:

705000131

FIELD INSPECTION FORMLoc ID 305465 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		COGCCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278114	WELL	SI	05/01/2022	GW	123-23013	PROMINENCE 4-8	PA
305465	LOCATION	AC			-	PROMINENCE-62N67W 8NWNW	EG

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 278114 Type: WELL API Number: 123-23013 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Prominence 4-8) has been plugged and abandoned; cut and cap operations are completed. COGCC form 42 notice of start of plugging operations doc #403183537 received 09/30/2022. (1) Fenced excavation was observed at the PA wellhead area. The wellhead flowline AIP/ removal is in progress. (1) 2" CS OLF flowline cut end (bullplugged) observed; and (1) 1" HDPE OLF flowline cut end observed in east wall of the PA WH excavation. The flowline(s) are marked/ pinflagged to the east of location. Remediation work is in progress (historical). No Oxy personnel were on location at the time of inspection.

Corrective Action:

Date:

Facility ID: 305465 Type: LOCATION API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403283297 received on 01/09/2023: On January 9, 2023, historical soil impacts were discovered following cut and cap operations at the Prominence 4-8 wellhead location. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	01/20/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000133	Location and fenced WH excavation; view west	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5991473
705000134	Flowlines exposed in the east wall of excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5991474