

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION Receive Date: 08/12/2022 Document Number: 402980084

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 10575 Contact Person: James Miller Company Name: 8 NORTH LLC Phone: (720) 984-7460 Address: 370 17TH STREET SUITE 5200 Email: jmiller@civiresources.com City: DENVER State: CO Zip: 80202 Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No []

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 460765 Location Type: Production Facilities Name: DF Ranch 10-11, 13, 42, 44 Number: County: WELD Qtr Qtr: NENE Section: 10 Township: 11N Range: 61W Meridian: 6 Latitude: 40.936004 Longitude: -104.182587

Description of Corrosion Protection

8 North's corrosion procedures are detailed in its Flowline Management SOP. Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service, and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, 8 North will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. 8 North retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

Description of Integrity Management Program

8 North's integrity management program is detailed in its Flowline Management SOP, which covers flowline installation, operation, maintenance, inspection, testing, and repairs. Prior to beginning any project involving flowlines, 8 North ensures the project plans, flowline installation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements of the Flowline Management SOP. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 461369 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 302923 Location Type: Well Site
Name: DF RANCH-611N61W Number: 10SESE
County: WELD No Location ID
Qtr Qtr: SESE Section: 10 Township: 11N Range: 61W Meridian: 6
Latitude: 40.930460 Longitude: -104.184390

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 05/10/2009
Maximum Anticipated Operating Pressure (PSI): 141 Testing PSI: 141
Test Date: 09/12/2018

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 04/05/2019

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

The entire 2" steel line was pulled and removed. The 1" poly line was unable to be pulled and was cut and capped below grade.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 461371 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 302922 Location Type: Well Site
Name: DF RANCH-611N61W Number: 10NWSE
County: WELD No Location ID
Qtr Qtr: NWSE Section: 10 Township: 11N Range: 61W Meridian: 6
Latitude: 40.934010 Longitude: -104.189130

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 05/22/2009
Maximum Anticipated Operating Pressure (PSI): 141 Testing PSI: 141
Test Date: 09/10/2018

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 08/18/2020

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

Flowline/Riser is locked out and tagged out.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 461368 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 415381 Location Type: Well Site
Name: DF RANCH Number: 1161-10-13
County: WELD No Location ID
Qtr Qtr: SWNE Section: 10 Township: 11N Range: 61W Meridian: 6
Latitude: 40.939460 Longitude: -104.189350

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 04/25/2010
Maximum Anticipated Operating Pressure (PSI): 130 Testing PSI: 130
Test Date: 09/20/2018

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 08/18/2020

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

Flowline/Riser is locked out and tagged out.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 461370 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 302813 Location Type: Well Site
Name: DF RANCH-611N61W Number: 10NENE
County: WELD No Location ID
Qtr Qtr: NENE Section: 10 Township: 11N Range: 61W Meridian: 6
Latitude: 40.941800 Longitude: -104.184310

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 04/27/2009
Maximum Anticipated Operating Pressure (PSI): 120 Testing PSI: 120
Test Date: 09/10/2018

OFF LOCATION FLOWLINE Abandonment Verification

Date: 02/07/2022

Abandonment Verification

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

Description of Abandonment Verification:

The subject flowline (12329869FL) was removed in its entirety. The 3" steel-flowline (buried ~4' deep) was cut and pulled via bellholes. Approximately 2860' of flowline was removed. The bellholes were backfilled and graded.

OPERATOR COMMENTS AND SUBMITTAL

Comments Form 44 submitted to report (1) flowline POST-ABANDONMENT verification.
- 12329869FL removed. Previously serviced the DF Ranch 10-11 well (05-123-29869).
Updated GIS SHAPEFILE attached.
Recent PRESSURE TEST attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 08/12/2022 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:  **Director of COGCC** Date: 1/23/2023

Conditions of Approval

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

402980084	Form44 Submitted
403056760	OFF-LOCATION FLOWLINE GIS SHP
403061967	PRESSURE TEST

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval

Total: 0 comment(s)