

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/23/2023

Submitted Date:

01/25/2023

Document Number:

701006392**FIELD INSPECTION FORM**Loc ID 321574 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 61250

Name of Operator: MULL DRILLING COMPANY INC

Address: 1700 N WATERFRONT PKWY B#1200

City: WICHITA State: KS Zip: 67206-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
OBryhim, Reesa		ROBryhim@mulldrilling.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207334	WELL	PR	03/01/2021	OW	017-06269	MULL UNIT 18	PR

General Comment:[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Lease sign by tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal signs by tanks		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Sticker on chemical drum		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Heater Treater	# 2		
Comment:	2-Treaters on south side of location		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator in metal shed		
Corrective Action:		Date:	

Type: Pump Jack	# 1	
Comment:	Parkersburg 160	
Corrective Action:		Date:
Type: LACT	# 1	
Comment:	LACT unit on north side of tank battery operated by Plains	
Corrective Action:		Date:
Type: Ancillary equipment	# 6	
Comment:	Electric panel, cathodic rectifier, chemical drum w/containment, electric circ pump at battery, telemetry at LACT unit, propane tank	
Corrective Action:		Date:
Type: Compressor	# 1	
Comment:	Skid mounted electric booster compressor in metal shed	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:	ECD west of oil tanks	
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Electric motor	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		38.847930,-102.894130
Comment:	Fiberglass open top water tank used as vent tank on west side of treaters				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		38.848360,-102.893960
Comment:	Central tank battery for (Mull Unit 15, 17, 18, 19, 20)				

Corrective Action:		Date:	
Paint			
Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Earth	Adequate	Walls Sufficient	Base Sufficient
Comment:			
Corrective Action:	Date:		
Venting:			
Yes/No			
Comment:			
Corrective Action:	Date:		
Flaring:			
Type			
Comment:			
Corrective Action:	Date:		

Inspected Facilities									
Facility ID:	207334	Type:	WELL	API Number:	017-06269	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central tank battery for (Mull Unit 15, 17, 18, 19, 20)								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	

Comment: [Unable to verify site conditions due to snow coverage](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701006406	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5997423