

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/13/2023

Submitted Date:

01/19/2023

Document Number:

696105684

**FIELD INSPECTION FORM**Loc ID 317277 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10690

Name of Operator: IMPETRO RESOURCES LLC

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bongers, Brent	361-935-5633	bbongers@impetroresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237704	WELL	PR	04/12/2000	OW	121-10207	WALTERS 12-21	RI
317277	LOCATION	AC			-	WALTERS-62N49W 21SWNW	RI

**General Comment:**

This is an Interim Reclamation and Stormwater Inspection for Location ID 317277.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Tank NFPA placards and signage are inadequate. Refer to attached inspection photos.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	02/19/2023

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Undesirable vegetation (e.g. russian thistle and kochia) observed throughout the produced water pits and well location. Refer to attached inspection photos.		
Corrective Action:	Comply with Rule 606.	Date:	01/27/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment observed near the well location (e.g. pipe). Refer to attached inspection photos.		
Corrective Action:	Comply with Rule 606 and remove any unused equipment.	Date:	02/03/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
	WELLHEAD	<= 1 bbl		
Comment:	Oil stained soil around wellhead. Refer to attached inspection photos.			
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.			Date: 02/03/2023

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	The western side of the earthen berm around the produced water tank has been breached and is inadequate. Refer to attached inspection photos and stormwater section for further information.	
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).	Date: 02/08/2023

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	237704	Type:	WELL	API Number:	121-10207	Status:	PR	Insp. Status:	RI
Facility ID:	317277	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

Environmental	
<b>Spill/Remediation:</b>	
Comment:	Remediation Project #7096 is still active and open. Continue to comply with 900 series rules and regulations.
Corrective Action:	<div></div> <div>Date: <div></div></div>
Emission Control Burner (ECB): <div></div>	
Comment:	<div></div>
Pilot: <div></div>	Wildlife Protection Devices (fired vessels): <div></div>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Evidence of rill and gully erosion was observed on the exterior perimeter walls of the produced water pits. The pit walls and berms need to be maintained and stabilized to minimize erosion and to ensure that sediment laden stormwater doesn't migrate off location.

Corrective Action: Immediately install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance.

Date: 01/13/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403296742	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5990191">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5990191</a>
696105690	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5990185">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5990185</a>