

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/19/2023

Submitted Date:

01/26/2023

Document Number:

701103677

FIELD INSPECTION FORM

Loc ID 334640 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Arauza, Steven		steven.arauza@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481721	SPILL OR RELEASE	AC	03/28/2022		-	Couey (G23W) dumpline	AC

General Comment:

Witness to dumpline pressure test.

Inspected Facilities

Facility ID: 481721 Type: SPILL OR API Number: - Status: AC Insp. Status: AC

Flowline

#1	Type: Dump Line	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: 2" Material: Carbon Steel
 Variance: Age: New Contents: Produced Water

Integrity Summary

Failures: Internal Corrosion Spills: Yes Repairs Made: Yes
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Dumpline replaced with stainless steel. Inspector on location to witness pressure test. Four-hour pressure test started at 1022am 1250 psi ended at 1422pm 1214 psi. Loss of 36psi (2.8%)

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103678	Flowline inspection 701103677 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5998388