

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

08/15/2022

Document Number:

403080966

**Off-Location Flowline**

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

**Operator Information**

OGCC Operator Number: 10633 Contact Person: James Miller  
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (720) 984-7460  
Address: 1801 CALIFORNIA STREET #2500 Email: jmiller@civiresources.com  
City: DENVER State: CO Zip: 80202  
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes ☒ No ☐

**OFF LOCATION FLOWLINE**

**FLOWLINE ENDPOINT LOCATION IDENTIFICATION**

Location ID: 332735 Location Type: Production Facilities  
Name: HORN-LIBSACK-64N65W Number: 27NESE  
County: WELD  
Qtr Qtr: NESE Section: 27 Township: 4N Range: 65W Meridian: 6  
Latitude: 40.280576 Longitude: -104.643447

**Description of Corrosion Protection**

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

**Description of Integrity Management Program**

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 473657 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 332674 Location Type: Well Site ☐  
Name: LIBSACK-64N65W Number: 27NESE  
County: WELD No Location ID  
Qtr Qtr: NESE Section: 27 Township: 4N Range: 65W Meridian: 6  
Latitude: 40.281970 Longitude: -104.642320  
Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material:  Date Construction Completed: 11/03/2006  
Maximum Anticipated Operating Pressure (PSI):  Testing PSI:   
Test Date:

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 05/25/2022

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

**Description of Abandonment Verification:**

The flowline serving the Libsack 8-6-27 (05-123-24104) was removed in its entirety via the open trench method. The trench was backfilled and the land surface graded.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 473656 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 332674 Location Type: Well Site ☐  
Name: LIBSACK-64N65W Number: 27NESE  
County: WELD No Location ID  
Qtr Qtr: NESE Section: 27 Township: 4N Range: 65W Meridian: 6  
Latitude: 40.281970 Longitude: -104.642320  
Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material:  Date Construction Completed: 12/26/2003  
Maximum Anticipated Operating Pressure (PSI):  Testing PSI:   
Test Date:

**OFF LOCATION FLOWLINE Abandonment Verification**Date: 05/25/2022**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

**Description of Abandonment Verification:**

The flowline serving the Libsack 43-27 (05-123-21838) was removed in its entirety via the open trench method. The trench was backfilled and the land surface graded.

**OPERATOR COMMENTS AND SUBMITTAL**

Comments Form 44 submitted to report (2) Flowline Post-Abandonment verifications.  
12324104\_FL was removed in it's entirety. It serviced the Libsack 8-6-27 (05-123-24104)  
12321838\_FL was removed in it's entirety. It serviced the Libsack 43-27 (05-123-21838)  
Updated GIS Shapefile attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 08/15/2022 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ **Director of COGCC** Date: \_\_\_\_\_

## Conditions of Approval

**COA Type**

**Description**

## Attachment Check List

**Att Doc Num**

**Name**

403136095	OFF-LOCATION FLOWLINE GIS SHP
403136096	OFF-LOCATION FLOWLINE GIS SHP

Total Attach: 2 Files

## General Comments

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)