

Construction and Stormwater Inspection

January 17, 2023

Operator: Verdad Resources LLC, #10651

Location ID: 483467

Inspection Document #: 709400002

Weld, CO

SWNE, Section 32, 2N64W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Kiwi/2920
Location ID: 483467



Photo 1. Photo taken from the entrance of location, facing East. Photo illustrates the access point to the location, the PVC pipe holding the Form 2A. Operator has yet to salvage topsoil but plans to. No observed tracking device on location.



Photo 2. Photo taken from from a portion of the access road, topsoil windrowed, will be salvaged and stockpiled on location.

Inspection Photos
Location Name: Kiwi/2920
Location ID: 483467



Photo 3. Photo taken from the western perimeter of location, facing south. Photo illustrates a berm and ditch BMP installed around the perimeter of the location.



Photo 4. Photo taken from the topsoil stockpile on location. Stockpile is unconsolidated and shall be stabilized, per rule 1002c.

Inspection Photos
Location Name: Kiwi/2920
Location ID: 483467



Photo 5. Photo taken of a sediment trap on location. . Photo illustrates the BMP is under construction but appears to be undersized to accommodate the size of the disturbance.



Photo 6. Photo taken of a sediment trap on location. See comments under photo 5.

Inspection Photos
Location Name: Kiwi/2920
Location ID: 483467



Photo 7. Photo taken from the eastern location. Photo illustrates debris/broken pipe that should be removed.



Photo 8. Photo taken from the eastern location. see comments under photo 7.