

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/06/2023

Submitted Date:

02/07/2023

Document Number:

705000158

FIELD INSPECTION FORMLoc ID 332556 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269143	WELL	SI	06/01/2022	OW	123-21632	PSC 15-11	PA
285831	WELL	SI	06/01/2022	OW	123-24048	PSC 37-11	PA
332556	LOCATION	AC			-	PSC-63N67W 11SWSE	EG

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photo uploaded

Inspected Facilities

Facility ID: 269143 Type: WELL API Number: 123-21632 Status: SI Insp. Status: PA

Facility ID: 285831 Type: WELL API Number: 123-24048 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Wells (PCS 15-11, 37-11) have been plugged and abandoned; cut and cap operations are completed. COGCC form 42 notice of start of plugging operations doc #403178058 received 09/26/2022. COGCC form 42 notice of flowline abandonment completed doc #403277450 received on 01/03/2023. The wellhead flowlines (OLF) have been removed. The facility/ tank battery is being decommissioned; tanks, equipment and OL flowlines being removed.

Corrective Action:

Date:

Facility ID: 332556 Type: LOCATION API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403282235 received on 01/06/2023: On January 6, 2023, historical soil impacts were discovered during the removal of the flowlines associated with the PSC 15-11 wellhead. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	02/07/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000159	Facility decommissioning work	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6012565