

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/07/2023

Submitted Date:

02/09/2023

Document Number:

702801239**FIELD INSPECTION FORM**Loc ID 311564 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210881	WELL	PR	04/13/1990	GW	045-06639	CLOUGH 3-28	PR
311564	LOCATION	AC			-	CLOUGH-66S94W 28NWNW	RI

General Comment:

On 2/7/2023, Reclamation Specialist O'Malley conducted a field inspection at TEP Rocky Mountain LLC's CLOUGH-66S94W/28NWNW Location #311564 in Garfield County, Colorado.

This is a follow up to inspection #702801100 to assess compliance with corrective actions regarding a leak at well API #045-06639. All corrective actions from inspection #702801100 have been addressed.

Refer to the "Inspected Facilities" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Inspected Facilities									
Facility ID:	210881	Type:	WELL	API Number:	045-06639	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Previous inspection #702801100 observed bubbles rising in water accumulated around the wellhead. Per FIRR #403302063 "A small leak on the Larkin head on the surface casing was sealed on 01/06/23". It was observed in this inspection that there is no evidence of a leak at the well. This corrective action has been addressed.								
Corrective Action:								Date:	
Facility ID:	311564	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

--	--	--	--	--	--	--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Gravel has been recently installed on the pad to mitigate potential pad destabilization and tracking issues. No stormwater issues observed at the time of this inspection. The location remains partially snow covered; unable to perform full stormwater inspection.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702801240	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6015855