

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /35-16H (ON1).

Location ID: 334468



Photo #8922 From entrance to location.



Photo #8923 From entrance to location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /35-16H (ON1).

Location ID: 334468



Photo #8925 Flow line heating insulation open ended.



Photo #8927 Multiple places with debris on location.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /35-16H (ON1).

Location ID: 334468



**Photo #8930 Multiple places with debris on location.**



**Photo #8932 Multiple places with debris on location.**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC Federal /35-16H (ON1).**  
**Location ID: 334468**



**Photo #8943 Multiple places with debris on location.**



**Photo #8934 Stained soil and gravel.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /35-16H (ON1).

Location ID: 334468



**Photo #8936** Sediment has been transported into ditch.



**Photo #8937** Sediment has been transported into ditch.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /35-16H (ON1).

Location ID: 334468



Photo #8939 Sediment migration in ditch.



Photo #8940 Sediment migration in ditch.