

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S97W /12SWNE

Location ID: 324378



Photo #8944 From entrance to location.



Photo #8945 From entrance to location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S97W /12SWNE

Location ID: 324378



Photo #8946 Loadline open ended.



Photo #8947 Multiple holes in secondary containment.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S97W /12SWNE

Location ID: 324378



**Photo #8948 Multiple holes in secondary containment.**



**Photo #8949 Multiple holes in secondary containment.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S97W /12SWNE

Location ID: 324378



**Photo #8950** Sediment has been transported in to reclamation area.



**Photo #8951** Sediment has been transported in to reclamation area.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S97W /12SWNE

Location ID: 324378



**Photo #8954 Sediment is choking off vegetation.**