

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2023

Submitted Date:

02/12/2023

Document Number:

701006419

FIELD INSPECTION FORM

Loc ID 321832 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	
Rogers, Bob	719-767-8851	brogers@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208151	WELL	PR	08/17/1991	OW	017-07086	MOUNT PEARL UNIT 11X-34	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:

Type	Access		
comment:	Gravel road through farm ground		
Corrective Action:			Date:

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:

Emergency Contact Number:

Comment:		Date:
Corrective Action:		

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

					corrective date
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:					Date:
Type: Prime Mover	# 1				
Comment:	Electric motor				
Corrective Action:					Date:
Type: Pump Jack	# 1				
Comment:	American 456				
Corrective Action:					Date:
Type: Ancillary equipment	# 2				
Comment:	Electric panel and cathodic rectifier				
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 208151 Type: WELL API Number: 017-07086 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central tank battery for \(Section 34\) 2100' ENE @ 38.880180/-102.768650](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date:

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701006475	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6018023