

Operator: Highpoint Operating Corporation

Location Name: Esterling 44-33H

Loc ID: 428695

Inspection: 696304645



Exhibit A



Exhibit B

CA: North Produced Water Tank is missing Labels - NFPA, Content and Capacity; Drain Pit at Compressor is missing Capacity Label.
Install sign to comply with Rule 605.h.

CA Resolution: Installed NFPA, content and capacity labels in accordance with Rule 605.h. (See Exhibit A) The capacity label on the drill pit compressor was installed in accordance with Rule 605.h. (See Exhibit B)