

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: PHOTO 4: TANK VALVE IS LEAKING PRODUCED WATER. LEFT MESSAGE WITH LAWRENCE BOWMAN. HE RESPONDED BY TXT WHILE I WAS STILL CONDUCTING THE INSPECTION. THE PUMPED SHOWED UP AND FIXED THE LEAK WHILE I WAS STILL ON LOCATION.

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Gas Meter Run # 1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date: _____

Type: Ancillary equipment # 1

Comment:

Corrective Action:

Date: _____

Type: Prime Mover # 1

Comment:

Corrective Action:

Date: _____

Type: Deadman # & Marked # 4

Comment:

Corrective Action:

Date: _____

Type: Bradenhead # 1

Comment: IS ACCESSABLE

Corrective Action:

Date: _____

Type: Progressive Cavity # 1

Comment:

Corrective Action:

Date: _____

Venting:

Yes/No NO

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695107584	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6019741