

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/14/2023

Submitted Date:

02/15/2023

Document Number:

705000163

FIELD INSPECTION FORM

Loc ID 321487 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293991	WELL	PR	11/13/2008	GW	013-06567	ROSS 41-24	EG

General Comment:

COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected FacilitiesFacility ID: 293991 Type: WELL API Number: 013-06567 Status: PR Insp. Status: EG**Flowline**

#1	Type: Non-Well Site	of Lines	
<u>Flowline Description</u>			
Flowline Type:	<u>Non-Well Site</u>	Size: <u>2"</u>	Material: <u>Carbon Steel</u>
Variance:		Age:	Contents:
<u>Integrity Summary</u>			
Failures:		Spills:	Repairs Made:
Coatings:		H2S:	Cathodic Protection:
<u>Pressure Testing</u>			
Witnessed:		Test Result:	Charted:
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment			
<u>Comment:</u>	Well (Ross 41-24) has been plugged and abandoned; cut and cap operations are completed. COGCC form 42 notice of start of plugging operations doc #402314964 received 02/18/2020. No flowlines/ risers observed at (PA) wellhead. Fenced bellhole excavations observed at FL pull points between Ross 41-24 WH and Ross 31-24 WH; Ross 31-24 flowline pipe has been removed. Inspector unable to get to Ross 31-24 WH due to poor field conditions. Facility/ battery located @ 40.123926, -105.054876 serviced multiple wells. No Civitas personnel were on location at the time of inspection.		
<u>Corrective Action:</u>			<u>Date:</u>

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000165	Signage at WH; view North	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6022350
705000166	Fenced bellhole excavations; OLF removal	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6022351