

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/13/2023

Submitted Date:

02/15/2023

Document Number:

702801264

**FIELD INSPECTION FORM**

Loc ID 334602 Inspector Name: O'Malley, Anna On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
4 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 10456  
 Name of Operator: CAERUS PICEANCE LLC  
 Address: 1001 17TH STREET #1600  
 City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		COGCC.inspections@caerusoilandgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
334602	LOCATION	AC			-	CEDAR SPRINGS RANCH-67S93W 11NWSE	RI

**General Comment:**

On 2/13/2023, Reclamation Specialist O'Malley conducted a field inspection at Caerus Piceance LLC's CEDAR SPRINGS RANCH-67S93W/11NWSE Location #334602 in Garfield County, Colorado.

This is a follow up to inspection #702801031 to assess compliance with previous wildlife protection corrective actions. Corrective actions from inspection #702801031 have been addressed.

The following compliance issues were observed during this inspection:  
 - Tank spilled, staining in secondary containment

Refer to the "Location" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment:

Control measures to prevent wildlife entry into separator piping have been installed. Corrective action from inspection #702801031 has been addressed.

Corrective Action:

Date:

Overall Good:

**Spills:**

Type

Area

Volume

Comment:

Produced water/condensate tank #81396 appears to have spilled from the top. Staining was observed down the side of the tank and stained gravel and snow was observed within secondary containment below the spill.

Corrective Action:

Remove stained materials and document integrity of containment structure. Properly dispose of oily waste in accordance with 905.e.

Date: 03/02/2023

In Containment: Yes

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 334602 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702801265	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6023072">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6023072</a>