

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/07/2023

Submitted Date:

02/10/2023

Document Number:

702801244

**FIELD INSPECTION FORM**
 Loc ID 335076 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335076	LOCATION	AC			-	CLOUGH-66S94W 29SENW	RI

**General Comment:**

On 2/7/2023, Reclamation Specialist O'Malley conducted a field inspection at TEP Rocky Mountain LLC's CLOUGH-66S94W/29SENW Location #335076 in Garfield County, Colorado.

This is a follow up to inspection #702801098 to assess compliance with corrective actions regarding soil staining and unused equipment.

The following compliance issues were observed during this inspection:

- Stained soil beneath equipment

Refer to the "Location" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Unused equipment previously observed in inspection #702801098 has been removed. Corrective action has been addressed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
Comment:	Previous inspection #702801098 observed stained soil beneath chemical injection equipment at separators. Inspector required Operator to conduct maintenance on equipment, cleanup stained material and review self inspection processes by 1/11/2023. Operator submitted FIRR #403302093 stating that stained soils beneath chemical injection unit were cleaned up on 1/11/23. Corrective action complete.  It was observed in this inspection that stained soil is present beneath chemical injection equipment. Chemical injection equipment observed to be actively dripping pink fluid. Original corrective action and date remain applicable.			
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.			Date: 01/11/2023

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 335076 Type: LOCATION API Number: - Status: AC Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403318700	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6017267">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6017267</a>
702801245	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6017258">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6017258</a>