

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

08/05/2021

Document Number:

402675811

Flowline System

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 10749 Contact Person: Gina Doerner  
Company Name: SIMCOE LLC Phone: (970) 852-0082  
Address: THREE ALLEN CENTER, 333 CLAY ST SUITE 3900 Email: gina.doerner@ikavenergy.com  
City: HOUSTON State: TX Zip: 77002  
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes  No

FLOWLINE SYSTEM

FLOWLINE SYSTEM IDENTIFICATION

Facility ID Number: 469080 Flowline System Name: PLA 9

FLOWLINE SYSTEM REGISTRATION

A representative legal location and associated latitude and longitude near the center of the Flowline System.

County: LA PLATA  
Qtr Qtr: SWNE Section: 21 Township: 32N Range: 10W Meridian: N  
Latitude: 37.004953 Longitude: -107.934248  
GPS Quality Value: Type of GPS Quality Value: Measurement Date: 09/21/2019

FLOWLINE DESCRIPTION AND TESTING

Date Construction Completed: 10/01/1991  
Pipe Material: Carbon Steel Bedding Material:  
Max outer Diameter (inches): 6.000 Type of Fluid Transferred: Natural Gas  
Max Anticipated Operating PSI: Testing Pressure: Test Date:

Description of Corrosion Protection:

The PLA 9 Flowline System is subject to the following corrosion protection practices: cathodic protection and chemical programs for internal corrosion.

Description of Integrity Management Program:

The PLA 9 Flowline System is subject to the following integrity management practices: continuous pressure monitoring.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

Bored and cased.

**FLOWLINE SYSTEM ABANDONMENT VERIFICATION**

Date: 11/06/2020

**Abandonment Verification**

The abandoned Flowline System was located within the jurisdiction(s) of the following local government(s).

| Jurisdiction | County   | Municipality |
|--------------|----------|--------------|
| County       | LA PLATA |              |

**Description of Abandonment Verification:**

Please see attached Location Flowline Abandonment Record and Third Party Verificaiton for the Decker NM to Miranda CDP 10-inch steel gas (PLA-9).

**OPERATOR COMMENTS AND SUBMITTAL**

Comments

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 08/05/2021 Email: gina.doerner@ikavenergy.com

Print Name: Gina Doerner Title: Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ Director of COGCC Date: \_\_\_\_\_

**Conditions of Approval**

**COA Type**

**Description**

|  |  |
|--|--|
|  |  |
|--|--|

**Attachment Check List**

**Att Doc Num**

**Name**

|           |                                    |
|-----------|------------------------------------|
| 402766053 | THIRD PARTY VERIFICATION           |
| 402766054 | ABANDONMENT IN PLACE DOCUMENTATION |
| 402771982 | FLOWLINE SYSTEM GIS SHP            |

Total Attach: 3 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

|  |  |                     |
|--|--|---------------------|
|  |  | Stamp Upon Approval |
|--|--|---------------------|

Total: 0 comment(s)