


Inspection Photos
Location Name: Redwin 22-4
API #069-06227



Wellhead sign



Tubing pressure

Inspection Photos
Location Name: Redwin 22-4
API #069-06227



Colorado Oil & Gas Conservation Commission
40.73796, -104.98706, 1607.0m, 246°
02/21/2023 09:37:22

Casing pressure



Colorado Oil & Gas Conservation Commission
40.73796, -104.98705, 1609.7m, 32°
02/21/2023 09:37:31

Bradenhead pressure