

# Inspection Photos

API: 071-07640

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/21/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07640 | Date: 2/21/2023

## Inspection Photos



**Photo 1.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07640 | Date: 2/21/2023



## Inspection Photos



**Photo 2.** Facing toward the wellhead. There was a water leak that had occurred which is the reason for the wet soils in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07640 | Date: 2/21/2023



## Inspection Photos



**Photo 3.** There is still a dripping water leak coming from this pipe joint.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07640 | Date: 2/21/2023



## Inspection Photos



**Photo 4.** There are signs that produced water flowed off the southwest side of the location down toward CR 31.9.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07640 | Date: 2/21/2023



## Inspection Photos



**Photo 5.** There are signs that produced water flowed off the southwest side of the location down toward CR 31.9.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07640 | Date: 2/21/2023



## Inspection Photos



**Photo 6.** Facing southeast toward the wellsite. . There are signs that produced water flowed off northwest side of the location. The flow pattern laid the vegetation over in the direction of the water flow..



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07640 | Date: 2/21/2023



## Inspection Photos



**Photo 7.** Facing southeast toward the wellsite. There are signs that produced water flowed off northwest side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07640 | Date: 2/21/2023



## Inspection Photos



**Photo 8.** There are signs that produced water flowed off northwest side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07640 | Date: 2/21/2023



## Inspection Photos



**Photo 9.** There are signs that produced water flowed off the northwest side of the location down toward CR 31.9.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07640 | Date: 2/21/2023



## Inspection Photos



**Photo 10.** This is the point along the county road where produced water flowed from the northwest corner of the wellsite.



**Photo 11.** This is the point along the county road where produced water flowed from the southwest corner of the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 12.** Facing northeast along CR 31.9 showing wet soils along the road.



**Photo 13.** Facing northeast along CR 31.9 showing wet soils along the road.

