

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/21/2023

Submitted Date:

02/22/2023

Document Number:

705000170

FIELD INSPECTION FORM

Loc ID 306713 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290601	WELL	SI	07/01/2022	GW	123-25149	CIZEK-USX T 1-8	PA
306713	LOCATION	AC			-	CIZEK-USX T-63N68W 1SENE	EG

General Comment:

COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 290601 Type: WELL API Number: 123-25149 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well (Cizek USX T 1-8) has been plugged and abandoned. COGCC form 42 notice of start of plugging operations doc #403237431 received 11/22/2022. COGCC form 42 flowline notice of flowline abandonment completed (on location) doc #403320843 received 02/14/2023. Multiple fenced excavations were observed on location. Fenced excavations were observed at the PA wellhead, fenced bellhole excavation at FL pull point and battery/ equipment areas. OLF wellhead flowline has been removed. No flowline risers observed at the (PA) wellhead or facility/ battery areas. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery have been removed. Excavation and remediation work (historical) is in progress.

Corrective Action: _____ Date: _____

Facility ID: 306713 Type: LOCATION API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403324503 received on 02/17/2023: On February 17, 2023, historical soil impacts were discovered during the removal of the flowline associated with the Cizek USX T 1-8 wellhead. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	02/22/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000180	Signage at PA well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6030305
705000181	Excavations; PA well and FL bellhole pull point	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6030307
705000182	Excavations at facility/ battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6030308