

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2023

Submitted Date:

02/23/2023

Document Number:

699805454**FIELD INSPECTION FORM**
 Loc ID 334599 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287313	WELL	PR	05/13/2007	GW	045-12963	SHORE 16-7 (PG16)	PR
288249	WELL	SI	06/01/2022	GW	045-13179	SHORE 16-6 (PG16)	SI
288250	WELL	PR	05/15/2007	GW	045-13178	SHORE 16-6BB(PG16)	PR
288251	WELL	PR	05/18/2007	GW	045-13177	SHORE 16-3 (PG16)	PR
288252	WELL	PR	05/24/2007	GW	045-13176	SHORE 16-3BB(PG16)	PR
288929	WELL	PR	05/26/2007	GW	045-13622	SHORE 16-7BB (PG16)	PR

General Comment:**COGCC Inspection Report Summary**

On 2/21/23 at approximately 13:30 hours, I, Inspector Corey De Paolo,
Conducted an on-site inspection at CAERUS PICEANCE LLC SHORE-67S95W /16SWNE.

Location # 334599 Garfield County Colorado

This inspection is response to complaint #403314212.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Chemical tank missing required information with a corrective action date of 3/22/23.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the
Compliance issues have been corrected to comply with COGCC rules.

This is a summary of the inspection report

Location				
Lease Road:				
	Type Access			
	comment:			
	Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
	Type OTHER			
	Comment: Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank. Batteries not in secondary containment			
	Corrective Action:		Date:	
	Type BATTERY			
	Comment:			
	Corrective Action:		Date:	
	Type WELLHEAD			
	Comment:			
	Corrective Action:		Date:	
	Type CONTAINERS			
	Comment: Chemical tank missing required information.			
	Corrective Action: Containers that are used to store, treat, or otherwise handle a hazardous material and which are required to be marked, placarded, or labeled.		Date: 03/22/2023	
	Type TANK LABELS/PLACARDS			
	Comment:			
	Corrective Action:		Date:	
Emergency Contact Number:				
	Comment: Caerus 911/970-285-2615			
	Corrective Action:		Date: _____	
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type LOCATION			
	Comment: Barbed wire fence around location			
	Corrective Action:		Date:	
Equipment:				
				corrective date
Type: Gas Meter Run	# 6			

Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:	Pressure transducers located on braden head. All braden head valves are accessible		
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit midstream		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Centralized containment					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	287313	Type:	WELL	API Number:	045-12963	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	288249	Type:	WELL	API Number:	045-13179	Status:	SI	Insp. Status:	SI
Complaint									
Comment:	This inspection is response to complaint #403314212.								
Corrective Action:					Date:				
Facility ID:	288250	Type:	WELL	API Number:	045-13178	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	288251	Type:	WELL	API Number:	045-13177	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	288252	Type:	WELL	API Number:	045-13176	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	288929	Type:	WELL	API Number:	045-13622	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Gravel						
		Ditches				
		Culverts				
Ditches						
		Gravel				
Berms						
		Berms				

Comment: [Limited storm water inspection due to location being covered with snow](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
This inspection is response to complaint #403314212. Refer to Signs/Markers for corrective actions.	depaoloc	02/22/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805456	Photos for Insp. #699805454	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6031079