

# Inspection Photos

API: 071-08776

Operator: XTO ENERGY INC

Inspection Date: 2/21/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023

## Inspection Photos



**Photo 1.** Facing north toward the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023



## Inspection Photos



**Photo 2.** Facing back at the southwest at the first switch back of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023



## Inspection Photos



**Photo 3.** There is sediment accumulation along this rip/rap outlet which needs maintenance (shoveled/cleaned out).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023



## Inspection Photos



**Photo 4.** Facing northwest along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023



## Inspection Photos



**Photo 5.** Facing northwest. The gravel ends at this point and a dirt road remains to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023



## Inspection Photos



**Photo 6.** Some of the check dams could use some hand maintenance to allow proper flow away from the roadside.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023



## Inspection Photos



**Photo 7.** The rock check dam at red arrow is filled in with sediment and there is some erosion below the check dam. Lat/Long:37.15901,-104.99182



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023



## Inspection Photos



**Photo 8.** There is some noxious weed debris (Canada thistle) found along this area of the road. This should be monitored and controlled later in the spring time.

Lat/Long:37.15901,-104.99182



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023



## Inspection Photos



**Photo 9.** Facing northwest along the road near the location which is at the top of the hill. This wide area along the side of the road should be seeded to provide stabilization.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023



## Inspection Photos



**Photo 10.** There is sediment accumulation along this rip/rap outlet which needs maintenance (shoveled/cleaned out).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023



## Inspection Photos



**Photo 11.** Standing at the location facing southeast. Maintenance was performed on the berm to allow drainage of stormwater away from the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023



## Inspection Photos



**Photo 12.** Facing south along the fill slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023



## Inspection Photos



**Photo 13.** Facing southeast at the west side of location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023



## Inspection Photos



**Photo 14.** Facing northeast at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08776 | Date: 2/21/2023