

CHEVRON USA INC
MCLAUGHLIN UNIT A-62N103W 13NWNW
Location # 314488



CHEVRON USA INC
MCLAUGHLIN UNIT A-62N103W 13NWNW
Location # 314488



Repaired line partially covered to control temperature of line.

CHEVRON USA INC
MCLAUGHLIN UNIT A-62N103W 13NWNW
Location # 314488



Removed section of damaged flowline