

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2023

Submitted Date:

02/23/2023

Document Number:

701103680

**FIELD INSPECTION FORM**Loc ID 314488 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	All Inspections
Sanford, Anita	(970) 675-3842	Anita.Sanford@scoutep.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228829	WELL	PR	04/01/2017	OW	103-05816	MCLAUGHLIN UNIT A 1	EG

**General Comment:**

**Inspected Facilities**Facility ID: 228829 Type: WELL API Number: 103-05816 Status: PR Insp. Status: EG**Flowline**

#1	Type:	1 of Lines
----	-------	------------

Flowline Description

Flowline Type:                      Size: 4"                      Material: Fiberglass  
 Variance:                      Age:                      Contents: Multiphase

Integrity Summary

Failures: Damage/Defects                      Spills:                      Repairs Made: Yes  
 Coatings:                      H2S:                      Cathodic Protection:

Pressure Testing

Witnessed: Yes                      Test Result: Fail                      Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation    ☒ 1102. Operations, Maintenance, and Repair    ☐ 1103. Abandonment

Comment: Test failed. After crew located another leak in line. Line was tested again on 2/13/2023 and chart was emailed to COGCC staff Michael Longworth

Corrective Action:                      Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103686	Flowline inspection 701103680 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6031371">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6031371</a>
701103687	MCLAUGHLIN UNIT A #1 Flowline Test Circle chart	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6031372">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6031372</a>