

Inspection Photos

API: 071-09921

Operator: VECTA OIL & GAS LTD

Inspection Date: 2/24/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09921 | Date: 2/24/2023

Inspection Photos



Photo 1. Facing east along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 2/24/2023

Inspection Photos



Photo 2. Facing north toward the location. The open top tank is empty and should be removed if unused.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 2/24/2023

Inspection Photos



Photo 3. There is red colored material on the soil surface possibly from cutting that needs to be cleaned up and removed. Topsoil should be separated and salvaged where there is disturbance and production equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 2/24/2023

Inspection Photos



Photo 4. The silt fence is in disrepair. An alternative perimeter BMP may be more appropriate for the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 2/24/2023

Inspection Photos



Photo 5. There is a pile of cactus debris at east side of the location that will need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 2/24/2023

Inspection Photos



Photo 6. There is supplies that remain at the northeast side of the location that need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 2/24/2023

Inspection Photos



Photo 7. North side of the location facing south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 2/24/2023

Inspection Photos



Photo 8. Facing toward the wellsite. No well sign is posted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 2/24/2023

Inspection Photos



Photo 9. There is drilling pipe and supplies that remain at the southwest side of the location that must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09921 | Date: 2/24/2023