

# Inspection Photos

Loc: 333719

Operator: [OGRIS OPERATING LLC](#)

Inspection Date: 2/23/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

333719 | Date: 2/23/2023

## Inspection Photos



**Photo 1.** Facing southwest along the main road. The area on the left cut slope of the road should be seeded for stabilization. Lat/Long:37.01249,-104.89533



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

333719 | Date: 2/23/2023

## Inspection Photos



**Photo 2.** Facing southeast. Drainage from the road shown in the previous photo concentrates at this access road which does not have a culvert. Lat/Long:37.01055,-104.89653



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

333719 | Date: 2/23/2023

## Inspection Photos



**Photo 3.** This culvert along the main road may be filled in or iced over and should be cleaned out when it dries out. Lat/Long:37.01149,-104.89621



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

333719 | Date: 2/23/2023

## Inspection Photos



**Photo 4.** Facing west toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

333719 | Date: 2/23/2023