

Inspection Photos

API: 071-09920

Operator: DESERT EAGLE OPERATING LLC

Inspection Date: 2/24/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 2/24/2023

Inspection Photos



Photo 1. Facing southeast toward the access road. Sign posted at road does not reflect current operator.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 2/24/2023

Inspection Photos



Photo 2. Facing southeast along the access road. The access road is not stabilized and soil is being pushed off the road. Soils should be segregated off the road before stabilizing the road with road base.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 2/24/2023

Inspection Photos



Photo 3. There is plastic pipe stored along the flowline and road that will need to be removed ASAP.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 2/24/2023

Inspection Photos



Photo 4. Facing southeast along the access road where flowline intersects the road to the processing plant and wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 2/24/2023

Inspection Photos



Photo 5. There are trees and soil pushed out along the area of trenching. All tree debris will need to be removed. Soil pushed out will need to be replaced.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 2/24/2023

Inspection Photos



Photo 6. Facing southeast along the flowline disturbance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 2/24/2023

Inspection Photos



Photo 7. Facing southeast along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 2/24/2023

Inspection Photos



Photo 8. There was a hole dug out by the location to place the ripper. This has created unnecessary disturbance that will need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 2/24/2023

Inspection Photos



Photo 9. Facing southeast toward the wellsite. There is soil mixing throughout this area and soils are not salvage and protected from degradation and compaction.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 2/24/2023

Inspection Photos



Photo 10. Facing northwest toward the wellsite. There is soil mixing throughout this area and soils are not salvage and protected from degradation and compaction.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 2/24/2023

Inspection Photos



Photo 11. Facing south toward the processing plant adjacent to the wellsite. The two well site flowlines tie into the processing plant.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 2/24/2023

Inspection Photos



Photo 12. Facing northwest toward the wellsite. There is soil mixing throughout this area and soils are not salvage and protected from degradation and compaction.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09920 | Date: 2/24/2023