

Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL-66S93W /26NESE

Location ID: 335310



Photo #9095 From entrance to location.



Photo #9096 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL-66S93W /26NESE

Location ID: 335310



Photo #9097 From entrance to location.



Photo #9098 Flow line heating insulation open ended.

Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL-66S93W /26NESE

Location ID: 335310



Photo #9099 Sediment has been transported off location and is now choking of vegetation.



Photo #9100 Berm needs maintained.

Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL-66S93W /26NESE

Location ID: 335310



Photo #9101 Sediment has been transported off location and is now choking of vegetation.



Photo #9102 Sediment has been transported off location and is now choking of vegetation.

Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL-66S93W /26NESE

Location ID: 335310



Photo #9104 Sediment has been transported off location and is now choking of vegetation.