

Inspection Photos

API: 05-061-06076

Operator: CHEMCO INC

Inspection Date: 3/1/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 3/1/2023

Inspection Photos



Photo 1. Facing southwest along the access road which has not been reclaimed. The crop has not re-established and there are undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 3/1/2023

Inspection Photos



Photo 2. Facing northeast at the location. There is equipment that still remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 3/1/2023

Inspection Photos



Photo 3. Facing east at the location. There is equipment that still remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 3/1/2023

Inspection Photos



Photo 4. Facing east at the location. This area approx. 75'x75' is bare of vegetation with no crop growth. There is reason to believe a historic spill has caused impacted soils.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 3/1/2023

Inspection Photos



Photo 5. South side of the location facing north. This area approx. 75'x75' is bare of vegetation with no crop growth. There is reason to believe a historic spill has caused impacted soils.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 3/1/2023

Inspection Photos



Photo 6. Facing east toward the surrounding undisturbed crop field. Wheat stubble is shown to be uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 3/1/2023