

Inspection Photos

API: 061-05142

Operator: WESTERN OPERATING COMPANY

Inspection Date: 3/1/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward access road and location. This area of the access road has eroded and is not stabilized and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05142 | Date: 3/1/2023

Inspection Photos



Photo 2. There is a metal cellar that remains at the location which needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05142 | Date: 3/1/2023

Inspection Photos



Photo 3. Facing east at the location. This area has not been reclaimed and sandy soils are susceptible to erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05142 | Date: 3/1/2023

Inspection Photos



Photo 4. Facing west at the location. This area has not been reclaimed and sandy soils are susceptible to erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05142 | Date: 3/1/2023

Inspection Photos



Photo 5. At the south side of the location there are several areas of hardened petroleum substance that needs to be cleaned up and removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05142 | Date: 3/1/2023

Inspection Photos



Photo 6. Closer view of the hardened petroleum substance that needs to be cleaned up and removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05142 | Date: 3/1/2023