

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 322-12

Location ID: 334908



Photo # 1554 From entrance to location.



Photo # 1555 Location.



Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC GM 322-12
Location ID: 334908



Photo # 1556 Lack of stabilization



Photo # 1558 Lack of stabilization

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC GM 322-12
Location ID: 334908



Photo # 1559 Lack of stabilization



Photo # 1560 Lack of stabilization

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 322-12

Location ID: 334908



Mar 3, 2023 at 9:15:41 AM
CO



Mar 3, 2023 at 9:16:32 AM
CO

Photo # 1564 Lack of stabilization

Photo # 1565 Lack of stabilization

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC GM 322-12
Location ID: 334908



Photo # 1560 Lack of stabilization



Photo # 1561 Lack of stabilization



Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC GM 322-12
Location ID: 334908



Photo #1566 Insufficient Tracking BMP



Photo # 1567 Insufficient Tracking BMP